

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

406

STATUS CONTROL TABLE

## TRANSMISSION PATH

(a) CONNECTION	TRANSMISSION PATH
(b) CELL TRANSMISSION INTERVAL	—
(c) CDVT	—
(d) REGISTRATION FLAG	NO
(e) LIST OF CELL-TRANSFERABLE CONNECTIONS	NONE

## VP

(a)	VPI=1	VPI=2
(b)	2	2
(c)	0	0
(d)	NO	NO
(e)	NONE	NONE

## VC

(a)	VPI/VCI=1/32	VPI/VCI=1/33	VPI/VCI=2/32	VPI/VCI=2/33
(b)	4	4	4	4
(c)	0	0	0	0
(d)	NO	NO	NO	NO
(f) LIST OF TRANSFERABLE CELLS	NONE	NONE	NONE	NONE

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10






FIG. 11




FIG. 12






FIG. 13

T7		TRANSMISSION PATH		VP			VC			
	(a)	TRANSMISSION PATH	1	2	(a)	1/32	1/33	2/32	2/33	
	(b)	—	2	2	(b)	4	4	4	4	
	(c)	—	0	0	(c)	0	0	0	0	
	(d)	NO	YES	YES	(d)	YES	NO	NO	YES	
	(e)	NONE	NONE	NONE	(f)	NONE	NONE	NONE	NONE	



T8		TRANSMISSION PATH		VP			VC			
	(a)	TRANSMISSION PATH		1	2	(a)	1/32	1/33	2/32	2/33
	(b)	—		2	2	(b)	4	4	4	4
	(c)	—		0	0	(c)	0	0	0	0
	(d)	NO		YES	YES	(d)	YES	YES	NO	YES
	(e)	NONE		NONE	NONE	(f)	NONE	NONE	NONE	NONE



T9		TRANSMISSION PATH		VP			VC			
	(a)	TRANSMISSION PATH		1	2	(a)	1/32	1/33	2/32	2/33
	(b)	—		2	2	(b)	4	4	4	4
	(c)	—		0	0	(c)	0	0	0	0
	(d)	NO		YES	NO	(d)	YES	YES	NO	YES
	(e)	NONE		NONE	NONE	(f)	NONE	000C	NONE	NONE






FIG. 14



*FIG. 15*

T13

	TRANSMISSION PATH	VP			VC			
(a)	TRANSMISSION PATH	1	2	(a)	1/32	1/33	2/32	2/33
(b)	—	2	2	(b)	4	4	4	4
(c)	—	0	0	(c)	0	0	0	0
(d)	NO	YES	NO	(d)	YES	YES	YES	NO
(e)	NONE	1/33	NONE	(f)	NONE	000C	NONE	NONE



T14

	TRANSMISSION PATH	VP			VC			
(a)	TRANSMISSION PATH	1	2	(a)	1/32	1/33	2/32	2/33
(b)	—	2	2	(b)	4	4	4	4
(c)	—	0	0	(c)	0	0	0	0
(d)	NO	YES	NO	(d)	YES	YES	YES	NO
(e)	NONE	NONE	NONE	(f)	NONE	NONE	NONE	NONE

